

## 64-67 GTO/Lemans

### **Console Lid Repair Kit Reattaches Lid to Console at the Hinge**

#### Installation Instructions:

1. Remove entire console from car.
2. Remove metal cover from console base.
3. Remove compartment lid.
4. With pliers, carefully break away the thin potmetal lip to which the compartment was attached.
5. Remove courtesy light bracket and lens from console base.
6. Insert repair bar on top of console base, but under metal cover.  
Insert repair bar, bevel up, slots forward.
7. Insert screws through existing holes in hinge, repair bar, console base and light brackets in this order.
8. Reassemble in reverse order from 5.